FINANCIAL SECURITY FORMS

Letter of Credit

A letter of credit must be issued by a Federal- or Pennsylvania-chartered lending institution. In addition to customary requirements for a letter of credit, the document must state:

Obligor:

Name of contractor and address

Beneficiaries: Millcreek Township

Millcreek Township Sewer Authority

3608 West 26th Street Erie, PA 16506-2037

Purpose:

Secure proper performance by the Obligor of all work in connection with

effecting, altering, modifying or terminating a connection and constructing

building sewers or mains for property known as

Term:

Not less than one (1) year from date of issuance.

Should work required under the issued permit and applicable regulations not be completed and certified as completed within one year after the date of issuance, the letter of credit shall automatically be extended for an

additional period of one year.

Exercise:

Upon written certification by Millcreek Township or the Millcreek Township Sewer Authority that work has not been performed in accordance with the issued permit and/or applicable regulations and standards, Millcreek Township and/or the Millcreek Township Sewer Authority, at its or their sole election and free from any claim by the obligor or the issuer, may demand and collect up to the full amount of the letter of credit.

Nonrenewal: Should the issuer elect not to renew the letter of credit, it shall give the beneficiaries at least thirty (30) days' prior written notice of its election not to renew, in which event Millcreek Township and/or the Sewer Authority may, upon written demand and free from any claim by the obligor or the

issuer, draw up to the full amount of the security.

Restricted or Escrow Account

A restrictive or escrow account must expressly name Millcreek Township as owner (subject to proper performance and release of the security) or specifically assign to Millcreek Township the right to recover up to the full amount of the account as required to defray or reimburse expenses, attorneys' fees and other damages sustained as a consequence of the work and/or secure payment of sums due pursuant to the permit.

MILLCREEK TOWNSHIP

APPLICATION FOR PERMIT TO MAKE, ALTER OR TERMINATE CONNECTION TO THE SANITARY SEWER SYSTEM

Erie County Index No. (33)			Permit No.
connection, alteration or terminal application. The undersigned pro-	system. A plan of the prenation and the proposed sew mises and agrees that if a pern Township Sewer Use Ordina	nises subject to the read that the facilities is attement is issued, the pance. Rules and R	or terminate a connection to the Millcreen to the propose that application and showing the propose tached hereto and is made a part of the proposed work shall be done in accordance to the sanitary Sewer than the terms of this application.
Permit Fee: \$	Tap-In Fee:	\$	Other Fees: \$
Owner Name(s):			
Owner(s) Address:			·
		_ Telepho	one:
Subject Property:			
Subdivision:		Lot No.	:
Street(s) Involved:			
Connection			
Contractor No.			
Contractor Address			
-		Telephon	ne:
Address for Billing:			
A Plan of the proposed propproperty owner unless the owner(s) la third party to submit this application. Date:	has/have submitted to the Mi	illereek Townshin	This application must be signed by the Sewer Authority a writing authorizing d by all obligations on the permit.
MSA	∆-MT 5165 -		

App. 502

APPLICATION FOR PERMIT TO MAKE, ALTER OR TERMINATE CONNECTION TO THE SANITARY SEWER SYSTEM

PAGE 2 OF 2

PLAN OF SUBJECT PROPERTY AND PROPOSED WORK:

(FO	R SEWER AUTHORITY USE	E ONLY)
Application GRANTED	DENIED	Date:
Contractor/Owner Financial Security on Fi	ile? YES _	NO
Reason(s) for Denial:		
Weate Analysis d		
This permit is valid for one year for one request of the owner and for g	from the above date of approod cause shown. hority Representative:	oval, and expires unless extended
(To be completed after connection and inspe	ection)	
Date of Sewer Inspection	Drain Insp	pection
Connection Location:		
Inspected Work APPROVED	DISAPPROVED	Reason(s):
Date:	Inspector Signature:	MSA-MT 5166

RELEASE AND ACKNOWLEDGMENT

The Undersigned(s) ("Owner") is/are the owner(s) of that property in Millcreek Township
Erie County, Pennsylvania commonly known as:
which is served by the Millcreek Township sanitary sewer system.
I/We have been advised by representatives of Millcreek Township and/or the Millcree
Township Sewer Authority that because of topography, grade or other unique circumstance
beyond control of Owner, Millcreek Township and the Millcreek Township Sewer Authority
installation of a backwater valve at the property would help to protect the property against backup
of sewage. Conditioned on this Release and Acknowledgment, Millcreek Township and/or th
Millcreek Township Sewer Authority have offered to provide the following:
In consideration of the above, Owner hereby agrees as follows:
1. Owner shall be solely responsible for installation, cleaning and future maintenance
of the backwater valve and all costs associated with installation, repair, operation and replacement
of the valve except for the Township's and Authority's contribution defined above.
2. Owner shall be solely responsible for installation of the valve and its accessories.
3. Owner releases and waives any and all claims and causes of action of any nature
against Millcreek Township and the Millcreek Township Sewer Authority which pertain to or
arise from installation of the backwater valve, operation, maintenance, repair or replacement of
the valve and potential damages to the floor of the building which might result from the absence
of or maintenance of footer drains and/or a sump pump system.
Date:(SEAL)
Owner Signature
Date: (SEAL) Owner Signature
The organia

Original in MTSA File Copy to Owner

MILLCREEK TOWNSHIP REQUEST FOR INSPECTION OF SEWER CONNECTIONS

The undersigned requests that Millcreek Township inspect the described property to determine whether any connections to the sanitary sewer system exist which violate the Sewer Use Ordinance. If the undersigned is not the owner, the written consent to and authorization of the owner is attached.

Property Address:	
Record Owner(s):	
Name of Requester(s):	
70	·
Requester's Phone #:	Requester's Fax #:
Person to Contact for Inspection:	
Contact's Relationship if not Owner:	·
Contact's Phone #:	Contact's Fax #:
Requested Times/Days for Inspection:	
Reason for Request:	
Is a clean-out accessible on the property?	(If not, see below)
If clean-out is accessible, where is it located?	
Is there a water source to the property?	
If no water source, how will requester/owner p	provide water source?
Fees paid with Request: \$	
Fee payment includes base fee plus:	
Request Date:	Signature of Requester
Send Request with Fee Payment and Owner Au Millcreek Township Sewer Authority 3608 West 26th Street	athorization, if required, to:

Erie, PA 16506-2037

MILLCREEK TOWNSHIP

OWNER'S AUTHORIZATION TO CONDUCT INSPECTION

Property Address:	
Owner's Name(s):	
Requester's Name:	<u>.</u>
TO: Millcreek Township Millcreek Township Sewer Author	ority
property, owned by the undersigned, be in been effected to the public sanitary sewer include such things as discharge into the waters, surface drainage or subsurface infiltration of ground or storm waters into You are hereby authorized to en requested inspection. The undersigned we will ensure that an authorized representation must be accessible at the time of the inspection.	and Requester will submit to you a written request that the above inspected to determine whether any unlawful connection(s) have a system. I/We acknowledge that an "unlawful" connection care sanitary sewer system of storm waters, roof runoff, ground drainage, as well as defective building sewers which allow the sanitary sewer system. The upon my/our property for the purpose of conducting the will be present to allow access into buildings on the property or we is present to do so. I/We understand that traps and clean-outs ction so that the building sewer(s) can be inspected. If the traps of carpeting, furniture or other items, these items will be removed.
present or accessible. If traps and clean-or Millcreek Township and the Millcreek To	result from attempts to inspect if the traps and clean-outs are not uts are not made accessible at the time of inspection, we release ownship Sewer Authority from all claims relating to damage to building sewer, which result from reasonable conduct of the
Signed at	this day of
	Owner
	Owner

MILLCREEK TOWNSHIP CERTIFICATION OF SANITARY SEWER CONNECTIONS

Subject Property:
Type of Building(s):
Name(s) of Owner(s):
Date of Inspection(s):
Inspector(s)'s Name:
The inspection of the property included:
Downspouts (note # and locations)
Floor drains (note # and locations)
Camera images from the sewer main
All downspouts and floor drains were inspected except as follows (indicate reasons)
No connections to the sanitary sewer prohibited by the Sewer Use Ordinance were noted OR
Connections to the sanitary sewer prohibited by the Sewer Use Ordinance were noted
Detail re. unlawful connections:
Limitations, if any, on the inspection and this certification (with reasons):
Date:
Name:
Original to Requester Copy to Property Owner

C Copy in Township File with Request and Authorization (Notice of Intended Inspection)

Dear Sanitary Sewer Customer:

The Millcreek Township Sewer Authority and Millcreek Township are responsible for conducting inspections of the sanitary sewer system to prevent storm or "clean" water from entering and overloading the sanitary sewer system. "Clean" water generally is water that has not been contaminated and does not require treatment prior to discharge. Rainfall, ground or subsurface drainage, sump discharges and roof runoff are examples of "clean" water.

The Township's Sewer Use Ordinance prohibits connection of "clean" water discharges into the sanitary sewer system. Despite this, many connections of "clean" water to the sanitary sewer have been found. No sanitary sewer system can accommodate both sanitary sewerage and "clean" water. Unlawful connections to the sanitary sewer system have resulted in:

- Backup of sewage and flooding of basements.
- Substantial costs to rate payers of transporting and treating "clean" water.
- Discharges to protect against sewage backups that lead to fines paid by the system.
- Sanitary flows exceeding our system's allowed capacity and prompting surcharges.
- Expensive capital projects that cause rate increases to all users of the system.

The Township and Authority are committed to identifying and eliminating these unlawful connections. We recognize that many property owners may not even know that there is an unlawful connection of "clean" water to the sanitary sewer. Your area and your property have been identified as having significant potential for an unlawful connection.

In the near future, you will receive a call from Phil Cardella, the Township Sewer Inspector, to schedule an inspection. You may also call the Authority's office and speak with Jan Agnello (835-6721, ext. 326) to make an appointment for an inspection. Our ordinance requires owners to allow access to their property for inspections and we hope you will cooperate with these efforts. Mr. Cardella and other inspectors will have identification when they visit to inspect. If there is any need to verify that an inspector is an authorized representative, you may contact this office during normal business hours. It is important that there be access to the clean-out in your basement at the time of the inspection.

Thank you in advance for your cooperation. Others in your area are also being contacted. Please understand that the process of inspection takes time with our limited staff.

	Very truly yours,
Dated:	
INSPECLT/SEWER	George W. Riedesel, P.E., Manager

App. 508 MSA-MT 5171

(Followup if no response to request for inspection)
(Date)
Owner Name Street Address City, State, Zip
Re: Inspection of Sanitary Sewer Connections
Dear:
Millcreek Township and the Millcreek Township Sewer Authority have reason to believe that your property may have a connection of "clean" or storm water to the sanitary sewer system.
The Millcreek Township Sewer Use Ordinance requires that owners allow access by the Township and the Authority to properties so that inspections can be conducted. An owner's failure or refusal to allow access or inspections can lead to imposition of fines for each day of violation.
Millcreek Township's Sewer Inspector has attempted to contact you to schedule an inspection, but no response to his request has been received. To avoid the need for proceedings under the ordinance, please contact Jan Agnello at this office (835-6721, ext. 326) to make an appointment for an inspection of your service lateral and connection. The business card for the inspector is enclosed. You may also try to reach him at his cell phone number. Access to the clean-out in your basement will be required at the time of the inspection.
If we do not hear from you by so that an inspection can be scheduled, we will have to begin enforcement proceedings regarding failure or refusal to allow access to your property. We hope you will make this unnecessary by responding promptly to this letter.
Very truly yours,
George W. Riedesel, P.E., Manager
cc: Richard Bridger

c: Richard Bridger Philip Cardella

(Letter re. inaccessible clean-out)
(Date)
Owner Name Street Address City, State, Zip
Re: Sanitary Sewer Inspection
Dear:
Recently, a Millcreek Township Sewer Inspector visited your home to inspect connections to the sanitary sewer system. At that time, there was no access to the clean-out in your basement.
Access to the clean-out is necessary for an inspection, and would also be necessary if you ever have a sewer problem.
Please locate the clean-out and make it accessible for inspection. Please then give me a call at 835-6721, extension 326 so that another appointment can be made to complete this inspection. Your prompt attention will be appreciated.

Very truly yours,

Janice K. Agnello Executive Assistant

(Notice where apparent violation noted other than from inspection	(N	Votice	where	apparent	violation	noted	other	than	from	inst	pection
---	----	--------	-------	----------	-----------	-------	-------	------	------	------	---------

(Date)

Owner Name Street Address City, State, Zip

> Re: Unlawful Connection to Sanitary Sewer

Dear :

It has come to the attention of Millcreek Township and the Millcreek Township Sewer Authority that your property may have a connection of storm or "clean" water to the sanitary sewer system. The Township's Sewer Use Ordinance prohibits and declares unlawful connections of ground, subsurface or surface drainage or of roof runoff or sump discharges to the sanitary sewer system. The ordinance also authorizes actions to terminate unlawful connections and imposes fines for each day of a violation.

Rather than pursuing enforcement proceedings, we request that you call Jan Agnello in this office at 835-6721, ext. 326 to schedule an inspection of your service lateral and connection. Access to the clean-out in your basement will be required at the time of inspection.

If an inspection should determine that there is no unlawful connection, no further action would be needed. If inspection discloses existence of an unlawful connection, we would provide you with detail of how you can eliminate that connection without legal proceedings being needed.

If we do not hear from you within 15 days after the date of this letter, we will have no choice but to begin actions to enforce the ordinance. We look forward to hearing from you.

Very truly yours,

George W. Riedesel, P.E., Manager

cc:

Richard Bridger Philip Cardella

(Letter	to	accompany	enforcement	notice)

(Date)

Owner Name Street Address City, State, Zip

Re: Unlawful Connection to Sanitary Sewer

Dear _____:

It has been determined by Millcreek Township and the Millcreek Township Sewer Authority that your property has a connection of ground or storm water to the sanitary sewer system. Millcreek's Sewer Use Ordinance prohibits such connections, imposes fines for each day of a violation and authorizes measures to terminate the connections.

I am enclosing with this letter an Enforcement Notice citing you with violation of the ordinance. The notice provides detail as to the violation and how it can be rectified.

Before taking action that might lead to imposition of substantial fines, we would like to work with you to assist you in terminating the unlawful connection. To rectify the violation, you must make repairs within 60 days after the date of this letter that will terminate the unlawful connection to the sanitary sewer and redirect ground or storm water in another way that complies with Township ordinances.

Please contact Jan Agnello in this office at 835-6721, ext. 326 when you know that the work will be done, so that an inspector can be present to monitor the disconnection and other work. If work is done without inspection and ends up not meeting standards, additional work would be required. If the unlawful connection is not disconnected within 60 days, fines for each day of violation as recited in the enforcement notice can be imposed. You may contact the Township's Inspector, Phil Cardella (873-4449), or Mrs. Agnello may be able to offer suggestions as to how the unlawful connection can be terminated.

Thank you in advance for your cooperation in this matter.

Very truly yours,

cc: Richard Bridger

ENFLTR/SEWER

Philip Cardella

George W. Riedesel, P.E., Manager

TOWNSHIP OF MILLCREEK 3608 West 26th Street Erie, PA 16506-2037

ADMINISTRATIVE ENFORCEMENT NOTICE (REMEDIAL ACTION REQUIRED)

Notice Date:	Index No.
то:	, Owner
YOU HAVE VIOLAT SEWER USE ORDINANCE (ED SECTION OF THE MILLCREEK TOWNSHIP ORDINANCE NO. 2004-4, AS AMENDED.
DATE OF YOUR VIOLATION YOU VIOLATED THE ORDING	N: NANCE BY
YOU ARE HEREBY DEBEFORE IMPOSITION OF A FINE FOR	IRECTED TO TAKE THE FOLLOWING ACTION ON OR TO REMEDY THE VIOLATION AND AVOID R VIOLATION:
YOU MUST OBTAIN CONNECTION. ALL WORK TO THIS OFFICE SO AN INSE HAVE REMEDIED THE VIOL 833-1111 ON MONDAY THRO ON TOWNSHIP HOLIDAYS. IF YOU DO NOT REM ABOVE, A CIVIL ACTION FO AND COSTS WILL BE FILED PRESCRIBED FOR THE VIOL	A PERMIT IF WORK WILL BE DONE TO A SEWER MUST BE INSPECTED, AND NOTICE MUST BE GIVEN PECTION CAN BE SCHEDULED. IFYOUBELIEVE YOU LATION, PLEASE CONTACT THE UNDERSIGNED AT OUGH FRIDAY FROM 8 A.M. UNTIL 4:30 P.M. EXCEPT MEDY THE VIOLATION BY THE DATE SET FORTH OR ENFORCEMENT AND FOR JUDGMENT FOR FINES IN THE OFFICE OF THE DISTRICT JUSTICE. FINES LATION ARE \$600.00 FOR EACH DAY THE VIOLATION FORCEMENT ACTION, THE TOWNSHIP IS ALSO
	Signature of Code Enforcement Officer
ENFNOT/MLK/SEWER	Title:

AUTHORIZATION AND CONSENT

Property Address:
The Undersigned(s) is/are the owner(s) of the above property and will be referred to in this document as the "Owner".
Owner has been advised by Millcreek Township and/or the Millcreek Township Sewer Authority (collectively referred to as "Millcreek") that one or more discharges of storm water from the above Property have been connected to the sanitary sewer system, in violation of Millcreek regulations.
Owner understands that this violation can be rectified only by termination of the unlawful connection(s).
Owner has advised Millcreek that Owner is nor or may not be able to afford the costs of repairs necessary to terminate the unlawful connection(s).
Owner authorizes Millcreek and its employees or contractors to:
1. Enter onto the Property and into the building(s) on the Property served by the sanitary sewer, to conduct inspections to identify any unlawful connection(s) to the sanitary sewer system and determine how such connection(s) can best be terminated; and
2. Obtain proposals or quotations from one or more plumbing firm(s) for the work needed to terminate the unlawful connection(s).
Owner understands that Millcreek will then advise Owner of the work believed to be necessary and of the cost proposals it has received. Owner then will have the right either to retain a firm to do the needed work directly for Owner or to then enter into a written contract with Millcreek under which Millcreek would secure a firm to provide the work and submit to Owner an assessment for such costs. If Owner later decides that Millcreek should have the work done and assess Owner for its costs, Owner understands that a lien would be filed against the Property if the assessment was not paid within 30 days. Owner also understands that interest accrues on unpaid assessments at the rate of ten percent (10%) per year.
Date:Owner Signature
Date:
Owner Signature

App. 514

CONSENT TO REPAIRS AND ASSESSMENT

Property Address:	
The Undersigned(sthis document as the "Ow) is/are the owner(s) of the above property and will be referred to inner".
"Millcreek") to inspect Ov	signed an Authorization and Consent which aship and the Millcreek Township Sewer Authority (collectively vner's Property and secure proposals or quotations for work to tions from the Property to Millcreek's sanitary sewer system.
Property. Millcreek has d Owner of the proposals or to terminate the unlawful c	gation determined that one or more unlawful connections exist at the scussed with Owner the results of its investigation and has advised quotations received from plumbing firms to do that work necessary connection(s). A copy of the quotation or proposal of the firm which easonable in price and quality of work is attached to this Consent.
Owner does not hav	e the financial ability to pay in full the costs of the needed work.
Property, Owner is response violation of Millcreek regulation of the work is not paid in fi	that if Millcreek secures performance of the needed work at the ible for costs of the work as it benefits the Property and rectifies a ations. Owner has been advised that if an assessment for the costs all within 30 days after the assessment date, a lien would be filed exert on the unpaid assessment would accrue at the rate of 10% per
firm whose proposal is attac unlawful connection(s) at th completion of the work and for said costs to Owner. If date, interest on the unpaid Millcreek Township shall ha	Owner hereby agrees that Millcreek should retain the plumbing hed to this Consent to perform work necessary to terminate the Property to the sanitary sewer. Owner understands that upon its payment to the retained firm, Millcreek will issue its assessment Owner does not pay the assessment in full within 30 days after its amount will accrue at 10% per year from the assessment date and we authority to file a municipal lien for such costs in the Erie leas which shall be a lien against Owner's Property until paid in
_	
Date:	Owner Signature
Date:	
Date.	Owner Signature

(Notice that no unlawful connection detected)			Page 16 of 50
	(Date)		
:			
Dear			
Thank you for your cooperation in allowing	an inspect	ion of your property's	sewer connections.
I write to confirm that Millcreek Township's indication of any connections to the sanitary Use Ordinance.	s inspectio sewer sys	n onstem which violate the	disclosed no Township's Sewer
Thank you again for your cooperation.			
	Sin	cerely,	
	•		
Copy for property file			

NOVIOLT/MLK/SEWER

DEVELOPER AGREEMENT

THIS AGREEMENT made and entered into the day of February, 2004
BETWEEN: DEVELOPER, INC., a Pennsylvania Business Corporation whose principal office is located at 0000 Street, Millcreek Township, Erie County, and Commonwealth of Pennsylvania, hereinafter referred to as "Developer" AND
MILLCREEK TOWNSHIP SEWER AUTHORITY, an Authority created under and by virtue of the Municipality Authorities Act of 1945, as amended, with its principal office located in the Township of Millcreek, County of Erie and State of Pennsylvania, hereinafter referred to as "Authority".
WITNESSETH:
WHEREAS, the Developer is the owner of land in Millcreek Township known generally as the Subdivision located at 0000 Street, which is further identified as part of land identified by deed recorded at the Erie County Recorder of Deeds in record book 000 on page 0000 and also as Erie County Index No. 33-000-000-000.00 and as Millcreek Map Parcel No. 000-000; and
WHEREAS, the Developer has submitted design plans to the Authority for approval of sanitary sewers to be installed in Street, (the "Sewer Extension"), to serve the development known as the Subdivision and the developer agrees to construct the Sewer Extension in accordance with the Authority's requirements; and
WHEREAS, the Developer has received conditional approval from the Supervisors of Millcreek Township for the final plan of the Subdivision by letter from the Engineer of Millcreek Township; and
WHEREAS, the Developer has obtained permit approval for the Sewer Extension from the Pennsylvania Department of Environmental Protection.
NOW THEREFORE, in consideration of their intent to be legally bound hereby and other good and valuable consideration, the parties hereto agree as follows:

Sewer Extension - the term Sewer Extension as used herein shall mean all the sanitary sewer pipe and manholes, and any fittings and connections related thereto. It shall also include, where applicable, all pumping stations, force mains, electrical equipment, fencing, valves and any facilities related thereto. Any and all sanitary sewer facilities proposed for construction by Developer which are to become part of the Millcreek Township Sanitary Sewer System are herein defined as the Sewer Extension.

2.

Developer further agrees that said construction shall be in compliance with the Authority's General Specifications for Sewer Main Installation, and the Township of Millcreek Specifications covering backfill, which are incorporated herein by reference, and that such construction shall be subject to inspection and approval by Authority or its agents. The safety of all persons present at and in the vicinity of the site of the work performed pursuant to this Agreement shall be the responsibility of Developer and any contractor employed by Developer, and it shall not be the responsibility of Authority or the Township of Millcreek. Developer and any contractor employed by Developer shall ensure that during the progress of the work there is compliance with the regulations of the Occupational Safety and health Administration relating to "Excavations, Trenching and Shoring," 29 C.F.R. {{1926.650 through 1926.653, and the regulations of the Pennsylvania Department of Labor and Industry relating to "Excavations and Construction," 34 PA. Code {{33.271 through 33.319. Authority shall have the right, but not the obligation, to inspect the work site for compliance with such regulations. The undertaking of inspections by the Authority's engineers or authorized representatives of the Authority shall not be construed as supervision of actual construction nor make the engineers or the Authority responsible for providing a safe place or safe conditions for the performance or work under this agreement or contract by contractor, or contractors' employees or those of the suppliers or subcontractors. It is the sole responsibility of the contractor to provide a safe place and safe conditions for the performance of work and the sole responsibility of the contractor to enforce suitable rules, including all rules promulgated pursuant to the Occupational Safety and Health Act, 29 U.S.C. §651 et seq. and implementing regulations, for the safe prosecution of the work and for the safety and health of the workers employed on the project.

3.

Developer further understands and agrees that it will assume all costs and expenses in connection with the construction of the Sewer Extension, including but not limited to the cost of all labor, material, equipment, charges and fees of any kind.

If any portion of the Sewer Extension is constructed within a state right-of-way, Developer agrees to restore the area within the state right-of-way according to the requirements of PennDOT, and further Developer agrees to warranty such restoration for a period of two years.

It is specifically understood and agreed that Developer hereto shall restore the surface of any public or private property, or way through which this Sewer Extension shall be constructed to the condition that existed prior thereto, and at its own expense.

It is specifically understood and agreed that Developer hereto shall contact any Property Owners in at least 48 hours in advanced of any planed disruption of any utility services or road closings. It is also agreed that Developer shall contact Millcreek Township and the Millcreek Township School District regarding said road closings.

It is recognized and understood that Developer may employ a contractor for the purpose of actually constructing the Sewer Extension but, it is also specifically understood and agreed that such employment shall not in any way absolve Developer of any of its obligations under this Agreement.

4.

Developer also agrees to protect and hold harmless the Authority and the Township of Millcreek, and their agents and employees from any and all costs and expenses occasioned by the repair, replacement or maintenance of the Sewer Extension due to defective materials and/or workmanship for a period extending eighteen (18) months beyond the date of its acceptance by the Authority.

5.

Upon completion of the work of construction and final inspection and acceptance by Authority, ownership of the Sewer Extension shall vest in the Authority and all right, title and interest of Developer therein shall cease and terminate; it being the intention of the Developer to convey title to the Authority and to dedicate the Sewer Extension to public use, and the approval and acceptance by the Authority shall be deemed to be acceptance of said dedication. The Developer, upon completion of the construction of the Sewer Extension, agrees to dedicate the rights-of-way in which the Sewer Extension is constructed, by recording a dedication map at the Erie County Recorder of Deeds, after said map has been approved and signed by the Supervisors of Millcreek Township.

6.

If any portion of the Sewer Extension is not constructed within a dedicated right-of-way, Developer agrees upon completion to provide the Authority with an executed Deed of Grant conveying ownership of the Sewer Extension and a twenty (20) foot wide easement, in which the Sewer Extension and appurtenances are constructed for the purpose of operating and maintaining the Sewer Extension. Thereafter, no connection to the Sewer Extension or any house branch shall be made at any time by Developer or any other party or person without first obtaining consent in writing from the Authority and/or Township of Millcreek.

7.

Developer also understands and agrees not only to construct at its own expense the Sewer Extension, but also agrees to pay to the Authority at the time of execution of this Agreement, a Developer Fee for the privilege of tapping into the existing sanitary sewage system, which fee includes services to be furnished by Authority, including design review, inspection, testing and asbuilt plan preparation.

The Developer Fee referred to above is calculated at \$3.50 per lineal foot of gravity sanitary sewer constructed, \$2.00 per lineal foot of forcemain constructed, and \$50.00 per service connection as follows:

FROM MH 0+00 TO MH 4+28 (Example)

428	lineal feet @ \$3.50 per foot =	\$1,498.00	
5	service connection @ \$50.00 ea.=	<u>\$ 250.00</u>	
		\$1,748.00	\$1,748.00

FROM MH 0+00 TO MH 4+28 (Example)

		```	
428	lineal feet @ \$3.50 per foot =	\$1,498.00	
200	Lineal feet @ \$2.00 per foot =	<u>\$ 400.00</u>	
3	service connection @ \$50.00 ea.=	\$10,000.00	
	Total Developer Fee:	\$11,898.00	

In the event the expenses incurred by the Authority as a direct result of construction of the Sewer Extension exceed the fee above, the Developer agrees to pay the additional expenses to the Authority.

8.

Developer also agrees to pay any Tapping Fees that may be due on Developer 's property from previous sewer extensions. This Tapping Fee must be paid to the Authority as part of this Agreement.

9.

It is specifically understood and agreed between the parties hereto that Developer shall construct all of the proposed Sewer Extension in a continuous manner and shall minimize construction delay to the greatest extent possible.

It is specifically understood and agreed between the parties hereto that Developer shall upon completion of the project, prepare an asbuilt drawing plan. The Authority's inspectors will indicate on the Developer 's original sewer design plans and engineer's cut sheets the actual field measurements and will turn over copies of all asbuilt records and measurements to Developer. It will be the responsibility for the Developer to prepare an asbuilt design plan on reproducible drawing media. All inverts and manhole rim elevations shall be field verified by the Developer and indicated on the plans. If any sewer lines, laterals, or manhole locations deviate from the original plans, it will be the responsibility of the Developer to have the changes accurately shown on the asbuilt drawings. All drawings shall show sewer line stationing of all manhole and lateral connections. All drawings will be "D" size (36" x 24") and will be at 1" = 50' scale. The Sewer Authority will maintain all asbuilt records of all sewers and sewer connections installed at the time of initial sewer construction.

11.

Developer agrees to obtain all permits applicable to the construction of the Sewer Extension.

12.

It is understood and agreed between the parties hereto that Millcreek Township will operate the Sewer Extension under a separate agreement between Millcreek Township and the Authority.

13.

In the event that Developer undertakes to construct the sewer extension as contractor, or, if Developer contracts with a third party for construction of all or part of the herein-described sewer extension, Developer agrees to indemnify and hold harmless Authority and the Township of Millcreek from any and all claims for personal injury of any person whether or not an employee of Developer, Authority or the Township of Millcreek, arising out of or related to the construction of the sewer system which is the subject of this Agreement, whether or not the injured party alleges and proves that the loss is attributable in whole or part to any act of omission or commission, breach of duty or negligence on the part of Authority and/or the Township of Millcreek, said indemnity shall hold Authority and the Township of Millcreek harmless from any and all suits, costs, expenses of defense, including attorney fees, judgments and costs, even if it is alleged that said Authority and/or Township were active or passively negligent.

Developer or Contractor agrees to take out, pay for and maintain until completion of the work required by this Agreement, comprehensive broad term public liability insurance and contractual liability insurance. The contractual liability insurance shall insure Developer against liability to Authority and the Township of Millcreek under the provisions of paragraph 13 of this Agreement. A standard certificate of insurance form must be provided to Authority prior to the start of construction. No exclusions shall be indicated on the certificate under public liability coverage. Additional insurance coverage's such as auto liability, excess liability and workers' compensation, including the amounts of coverage provided, shall also be indicated on Developer's certificate of insurance. The comprehensive broad form public liability insurance shall be at least in the amount of \$3,000,000 each occurrence for bodily injury, \$1,000,000 any one account of property damage, the aggregate limit of not less than \$3,000,000. Developer agrees that like insurance requirements, except the contractual liability insurance requirements apply to all contractors connected with the work described herein. Prior to commencement of the work which is the subject of this Agreement, Developer and all contractors shall provide Authority with proof of compliance with the insurance provisions of this Agreement, satisfactory to Authority.

15.

This Agreement is binding on all the heirs, successors and assigns of all parties to this Agreement.

16.

It is agreed by the parties hereto that with respect to any controversy arising in relation to or out of this Agreement, that the laws of Pennsylvania shall apply.

17.

The Developer hereto agrees to indemnify, protect and hold harmless the Authority, its members and employees from any and all claims, lawsuits and other liability including costs of defense arising from construction of the Sewer Extension. Developer shall require the same indemnification from any and all contractors employed by Developer in construction of the Sewer Extension.

18.

Developer is specifically aware of the provisions of Ordinance No. 2004-4 of the Township of Millcreek, enacted March 30, 2004, which inter-alia, prohibits the introduction of any storm water, surface drainage, ground drainage, roof runoff, or subsurface drainage into the public sanitary sewer system. Developer warrants to the Authority that any and all construction done under the within Developer Agreement, whether done by Developer or by Developer's subcontractors or assigns, shall be in compliance with said Ordinance No. 2004-4; Developer hereby agrees to indemnify Authority and the Township of Millcreek for the actual cost of correcting any construction done by Developer, its subcontractors and assigns, in violation of the aforesaid Ordinance No. 2004-4, the Millcreek Township Public and Private Improvements Code or the Rules and Regulations Governing the Millcreek Township Sanitary Sewer System.

The Authority agrees to use its best efforts to charge and collect tapping fees from the owners of properties along the Sewer Extension who request a connection. The Developer agrees to indemnify and hold harmless the Authority from all costs and expense including costs of defense, by reason of any cause of action or claim brought against the Authority to prevent collection of tapping fees. The tapping fees will be collected by the Authority in accordance with the Authority's procedures and existing laws. The amount of the tapping fees to be collected will be determined by dividing the cost and fees of the Sewer Extension by the total property frontage benefited by the Sewer Extension. However, no tapping fee will be charged for any service to the property owned by the Developer as of the date of this Agreement. Any tapping fees collected by the Authority will be refunded to the Developer for a period of ten (10) years following completion of the Sewer Extension.

IN WITNESS WHEREOF, the parties hereto have hereunto set their hands and seals the day and year first above written.

	DEVELOPER
	SIGNATURE / TITLE
WITNESS:	
	MILLCREEK TOWNSHIP SEWER AUTHORITY
	CHAIRMAN
ATTEST:	
SECRETARY	

DEVAGRT/MLK/SEWER

XII. CONSTRUCTION STANDARDS


Performance standards for building and branch sewers are as set forth in Part 3.

Standards for traps and clean-outs are as set forth on the attached drawing.


Additional and updated standards for materials and construction shall be established by amendment of these Rules and Regulations.

12-1

SANITARY SEWER BUILDING CONNECTIONS SEWER TRAP AND CLEANOUT ASSEMBLY



OUTSIDE BUILDING OR MOBILE HOME



MSA-MT 5188

INSIDE BUILDING

App. 525

Enforcement Pending

Enforcement Repaired

Enforcement Suspended

No Problems Found

Inspections In Process

Township Repair

Case 1:05-cv-00059-MBC Document 38-12 Fi 16004 1630 1771 17718 17714 17718 177	iled 03/31/2006 Page 26 of 50 38 46 40 1225 05 23	ADDRESS
Charles Street	Amherst Road Atlantic Avenue Beaver Drive Beaver Drive Brooks Street Budd Drive Canterbury Drive	STREET
Gruver/Sharrow Yamma Przybyszewski Moon Fanne Mae/Hamil Craciun Hess Krizanik Pellegrino Stiller Dylewski Stinson Montagna/Orton Oblinski Perfetto Danylko Rutkowski Thompson Nichilo	Kukuda Johnson	NAME
3/4/2005 2/14/2005 3/28/2005 5/23/2005 2/15/2005 3/4/2005 3/22/2005 3/10/2005 3/18/2005 3/18/2005 3/10/2005 3/1/2005 3/1/2005 3/1/2005 2/21/2005 2/21/2005 2/21/2005	1/27/2003 11/11/2003 5/27/2005 1/21/2003 9/8/2003 4/22/2003 5/21/2002	1ST INSPECT
2/23/2005 4/6/2005 6/8/2005 4/7/2005 3/17/2005 3/17/2005 4/13/2005 4/28/2005 4/21/2005 4/13/2005 3/17/2005 3/17/2005 2/23/2005 3/3/2005 3/3/2005	6/7/2005 illegal connecti	TV INSPECT
4/13/2005 4/13/2005 2/25/2005	5/25/2004 1/6/2005 4/11/2005 6/7/2005 illegal connection - reinspect 5/2 - no problem ? 9/24/2003 4/25/2003 9/30/2002	ENFORCEMT
5/10/2005 6/20/2005 4/22/2005	5/25/2004 4/11/2005 - no problem ? 9/24/2003 4/25/2003 9/30/2002	REPAIR
6" VCP Repair no problem found suspended action no problem found inconclusive no problem found dirty lines/must clean no problem on old tape	Langdon/Wms no major at this time	NO VIOLATION
Reminder Letter 2/8/06 (Needs to find c/o) Township to make Repair Sheriffs Sale - Bank - Hammel/Hagmann plumber could not locate minor problem Reminder Letter 2/8/06 (C/O Located or Installed) sump pump connected to sanitary-Motsch except a lot of roots in clay portion of lateral some sags in pipe newer construction - pvc pipe cleaned lines then retelevised sags in pipe - no enforcement no problem found 6/16/05	Sump pump connect to floor drain (Langdon/Wms) Outside drain/wait for nice weather-concrete heavy pipe corrosion & some sags in line fllegal connection - reinspect 5/2 - no problem? Footers tied into sanitary Sump pump connect to sanitary Sump pump connect to sanitary	NOTES
3/16/2005 Jim Brozell 3/23/2005 5/24/2005	6/15/2005	

^ 									
	some sags in pipe - no enforcement lateral to dirty to see clearly	Suspended Action	4/15/2005	2/10/2005	3/23/2005 1/5-2/7/05	12/8/2004	Smith	Dixson Drive	5140
4/11/2005	needs to repair sump-done-now clean mh	has check valve	4/21/2005		4/21/2005	12/10/2004	Morschauser	Dixson Drive	5130
	Goes out high	no problem found			5/5/2005 5/5/2005	12/3/2004 12/16/2004	Brown Mever	Dixson Drive	Ca: 5120
	Completed		2/9/2005	12/16/2004	12/14/2004	11/29/2004	Roesch	Dixson Drive	
Don Murray	Working on Problem (12/15/05)	cannot find cleanout		6/24/2005	5/5/2005	12/3/2004	Bizjak	Dixson Drive	
	source sage in pipe - its enforcement	Suspended Action			12/15/2004	12/6/2004	Chludzinski	Dixson Drive	
	Goes out high	no problem found			3/3/2005	12/7/2004	Martin	Dixson Drive	CV 5102
	Goes Out High	Suspended Action		5/5/2005	4/27/2005	12/6/2004	Fischer	Dixson Drive	
		Suspended Action		12/3/2004	11/30/2004	11/29/2004	Bender	Dixson Drive	
	No Response Lately (RAR 2/10/06)	Suspended Action		2/25/2005	2/17/2005	2/9/2005	Bizzaro-daughter	Dixson Drive	-ME 4918
	Langer - not conclusive	Suspended Action		2/7/2005	1/26/2005	1/7/2005	Gomez	Dixson Drive	C 4903
			4/12/2005	12/22/2004	12/21/2004	12/6/2004	Gannoe	Dixson Drive	
Pilewski	Pilewski Plumbing		6/28/2005	4/13/2005	4/6/2005	3/22/2005	Dinges/Fox	Crowell Street	OCI 5603
	needs to find cleanout - 4/11 sent letter	no problem found			6/15/2005	3/31/2005	Huston	Crowell Street	ımer 5602
		No Problems Found			9007/07/01	10/3/2005	Costlow	Court Avenue	nt 3
					10/00/000	10/3/3005	Coction	Court Avenue	
		no problems found			11/3/2005	10/13/2005	Blackman	Court Avenue	-12 3028
	Footers tied into sanitary		3/27/2001			3/21/2001		Colonial Avenue	Ë 3204
	getting estimates -J & S Plumbing did repair		Mar-05	11/24/2004	11/24/2004	11/15/2004	Hartwig	Clinton Street	ed (5541
Grieshober	#NAME?		8/11/2005	11/3/2004	11/3/2004	10/20/2004	Mansfield	Clinton Street	
Omni Plumbina			12/20/2004	10/28/2004	10/21/2004	10/13/2004	DiLoreto	Clinton Street	31/2 5420
	Reminder Letter 2/8/06 (TV Inspection)					5/26/2005	Cohick	Church Street	2006 1636
	Ketsel Repaired & Needs Inspected?			5/5/2005	4/27/2005	4/19/2005	Estock	Church Street	1625
	some sags in pipe	no problem found no problem found			4/13/2005 6/14/2005	3/11/2005 6/9/2005	DiCara Yaple	Church Street Church Street	Page 1617
		no problem found			5/12/2005	4/15/2005	Ricchiuti	Church Street	
4/25/2005	sags in pipe - no enforcement	no problem found			5/25/2005	4/5/2005	Feisler	Church Street	
			İ		8/23/200E	A/20/2005	Kloockor	Church Street	50 1523
PLUMBER	NOTES	NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	ADDRESS
Township Repair	Inspections In Process	No Problems Found	No Pro	Enforcement Suspended	Enforcement	Repaired	Enforcement Repaired	Enforcement Pending	Enforce

App. 528			ė.			12/16/2005	Bujalski	Lucky Lane	5409
Ed Ketsel	serious back up problem Ketsel Fixed Second Repair? Needs Inspected? Sump and down spouts to sanitary Footers tied into sanitary	no problem found sump pump-fixed	6/1/2001 9/21/2001	5/24/2005	3/9/2005 5/17/2005	3/7/2005 3/7/2005 3/29/2005 4/27/2001 8/9/2001	Pett Magorien	Indiana Drive Indiana Drive Indiana Drive Loveland Avenue Loveland Avenue	Case 1:0 4 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	Sump pump connect to sanitary Sump pump connect to sanitary Footers tied into sanitary Sump pump & footer drains to sanitary Downspouts to sanitary Sump pump to sanitary Sump pump to sanitary Sump pump to sanitary		12/4/2000 1/21/2001 4/1/2002 11/4/2004 4/13/2000 5/8/2001 9/15/2000 2/16/2001			11/6/2000 3/27/2000 1/31/2002 4/14/2004 4/7/2000 2/11/2001 8/7/2000 1/30/2001		Falmouth Road Glenruadh Avenue Gore Road, West Garloch Drive Hartley Lane Hilltop Road Holiday Drive Homestead Drive	
5/19/2005	Reminder Letter 2/8/06 (TV Inspection)	suspended action can't find cleanout		6/24/2005	6/15/2005	5/9/2005 5/17/2005	Jobes Prylinski	Exeter Road Exeter Road	ocume 5306 5419
Chris Carlin Bill Morewood	Carlin did repair Carlin performed repair and replaced BWV needs to find c/o	suspended action BWV Program Bill Morewood Repairec	8/9/2005	12/13/2004 2/17/2005	12/7/2004 2/16/2005	11/29/2004 12/3/2004 12/3/2004 12/17/2004	Marchini Noble Saylor		
Al Kurtz Jack Langer Self (Wiler)	some sags in pipe - no enforcement Goes out high Langer Plumbing Goes out high	goes out high repair complete no problem found No Problem Found	6/20/2005 6/29/2005 4/12/2005	5/5/2005 12/16/2004 2/17/2005	3/31/2005 5/4/2005 12/15/2004 2/16/2005 5/18/2005 1/20/2005 1/27/2005	1/12/2005 12/2/2004 12/6/2004 1/11/2005 12/1/2004 12/13/2004 12/13/2005	Conley Briggs Kaye Wiler Munn Bricker	Enfield Lane	Filed 03/31/2 2032 2022 2033 3 3 5 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
Self (Trudnowski) Chris Carlin Jim Brozell	Goes Out High- sump pump goes to sanitary Goes Out High Goes Out High - Township to make Repair Goes Out High Goes Out High	6" VCP Repair no problem found no problem found	6/27/2005 7/7/2005	5/12/2005	5/19/2005 5/4/2005 4/27/2005 6/1/2005 5/18/2005	12/1/2004 12/13/2004 1/24/2005 1/22/2004 2/4/2005	Trudnowski Culbertson Crankshaw Brabender Weigold	Enfield Lane Enfield Lane Enfield Lane Enfield Lane Enfield Lane	•
	need to repair c/o - done & retelevised 2/11/05	no problem found	į		12/8/2004	11/29/2004	Langer	Dixson Drive	28 of 50 5141
PLUMBER	NOTES	NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	ADDRESS
Township Repair	Inspections In Process	No Problems Found	No Pi	Enforcement Suspended	Enforcemen	Enforcement Repaired	Enforceme	Enforcement Pending	Enforc

App. 529									
	Footers tied into sanitary		5/1/02			4/8/2002		Roslindale Avenue	4919
		no problem round		2/3/2006	11/2/2005	9/13/2005	Reynolds	Pershing Avenue	1661
	Bankruptcy - Home Vacant			6/3/2005	5/26/2005	5/6/2005	Winschel	Pershing Avenue	
Mike Dwyer	2nd Repair fixed outside	12/19 - tv repair		3/16/2005			Rogers	Pershing Avenue	as 1631
	Chris Carlin plumbing		1/13/2006	5/12/2005	4/21/2005	3/15/2005	Richter	Pershing Avenue	
			11/1/2005	5/17/2005	4/27/2005	4/15/2005	Green	Pershing Avenue	
	sump pump to sanitary	Chris Carlin repaired	5/4/2005	4/20/2005	4/27/2005	4/15/2005	Zaunegger	Pershing Avenue	
	Chris Carlin plumbing		7/26/2005	5/5/2005	4/28/2005	4/20/2005	Hartline	Pershing Avenue	
		no problem round	2/14/2006	11/30/2005	10/14/2005	9/28/2005	Fuller	Pershing Avenue	000 15 13
		-	11/22/2005	5/12/2005	5/4/2005	4/19/2005	Zimmerman	Pershing Avenue)59 1603
	some sags in pipe	no problem found			5/19/2005	5/3/2005	Soltys	Pershing Avenue	
	Working on Problem 1/3/06			6/3/2005	6/1/2005	5/3/2005	Duncan	Pershing Avenue	
	can't find cleanout	water in trap	11/1/05	4/28/2005		4/28/2005	Jacquel	Pershing Avenue	
	sags in pipe - no enforcement	12/20 ty repair	12/20/2005	4/21/2005	4/21/2005	4/11/2005	Jasinski	Pershing Avenue	
		isoppolitaina			3/31/2005	3/10/2005	Versidi	Dereking Avenue	
		no problem found			3/17/2005	3/8/2005	Sickler	Pershing Avenue	um 1505
·	Enforcement suspended	Plumber revideo		12/8/2004	11/18/2004	11/16/2004	Lepper	Perkins Street	eni 5104
Herman	repaired sump pump & replaced clean out		2/4/2005		2/4/2005	1/25/2005	Shaw	Perkins Street	38. 4724
	suspended enforcement action 6/8/2005	6/2-re tv repair		5/5/2005	4/28/2005	4/15/2005	Blackburn	Patton Street	-12 5475
		no problem found			5/26/2005	5/3/2005	Spronatti	Patton Street	
Ed Ketsel	G		6/15/2005	4/13/2005	3/30/2005	3/15/2005	Sallach	Patton Street	
La 1/0/901	Working on Problem 1/11/06			3/29/2005	3/18/2005	3/11/2005	Mahoney	Patton Street	
Ed Koteol	Ed Kestel plumbing		7/26/2005	4/13/2005	4/7/2005	3/21/2005	Laskowski	Patton Street	
	repaired floor drain	no problem after repair	4/21/2005		4/20/2005	3/8/2005	Burkhardt	Patton Street	
	eventhing repaired 2004 all okay	no problem found		:	!	4/19/2005	DiTomo	Patton Street	
	Working on Problem 1/24/06	ווס טומטוניו וסמומ		4/13/2005	3/30/2005	3/10/2005	Koch :	Patton Street	/20 5437
	will can when caps are open	no problem found			6/8/2005	4/15/2005	Timon	Patton Street	
	will call when cape are open					10/17/2005	Rimdzius	Patton Street	6 5414
	Sump pump to sanitary		5/7/2001			12/15/2000		Mineo Drive	Pa 633
	dirty line+				1/26/2005	1/8/2005	Grannis/Realtor	Mill Street	g 5121
	Sump pump to sanitary		7/31/2002			7/31/2002		McKee Road	e 29 3104
			A/26/2002			3/3/2002		Marchall Drive	9 of 50
PLUMBER	NOTES	NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	ADDRESS
Township Repair	Inspections In Process	No Problems Found	No Pr	Enforcement Suspended	Enforcemen	t Repaired	Enforcement Repaired	Enforcement Pending	Enforce

730 730	App								•
Motsch	Footers tied into sanitary		3/25/2003			1/24/2003	Mingarell	Spring Valley Drive	1205
Motsch	Motsch Working on Problem?		3/25/2003	6/15/2005	6/8/2005	5/23/2005	Blatt	Spring Valley Drive	1199
	Working on 2nd Problem			7/8/2005	6/29/2005	6/2/2005	Dzuricky	Spring Valley Drive	
	sump connected to floor drain			5/26/2005		5/23/2005	Daley	Spring Valley Drive	
	Working on Problem 1/16/06			6/24/2005	6/1/2005	5/11/2005	Colussi	Spring Valley Drive	
	Working on Problem 12/22/05			6/3/2005	5/25/2005	5/6/2005	Kraus	Spring Valley Drive	
	- : !	no problem found			6/2/2005	5/20/2005	Leemhuis	Spring Valley Drive	
5/25/2005	plumber opened c/o	can't find cleanout		2/3/2006	1/16/2006	5/24/2005	Onuschak	Spring Valley Drive	
	I coters ned lito salitary	no problem found			6/1/2005	5/16/2005	Roll	Spring Valley Drive	
	Sump pump to sanitary		4/8/2003			2/7/2003 2/21/2003	Sorenson	Spring Valley Drive Spring Valley Drive	0059
Jackson			71717	1,0,1000			, ,		M-6
-		ווס פו סטוכוווט	3/14/3006	3/8/2005	11/3/2004	10/27/2004		Southview Drive	
raje.	difficult to deal with	no problems			3/15/2005	11/2/2004	Bove	Southview Drive	
Dwver	Reminder letter 8/1/05	re-tv 3/18/05	9/26/2005	2/8/2005	1/21/2005	12/15/2005	Alimahmoodi	Southview Drive	
	going to clean and retelevise	suspend enforcmt		2/10/2005	2/7/2005	12/10/2004	Danowski	Southview Drive	O 1305
Mike Dwver	,		10/20/2005	2/8/2005	11/18/2004	11/10/2004	Miller	Southview Drive	un 1304
				2/8/2005	12/14/2004	11/10/2004	Pratt	Southview Drive	ner 1252
Bill Morewood			10/5/2005	2/8/2005	11/18/2004	11/4/2004	Hermann	Southview Drive	nt 3 1240
Reminder	Reminder letter 8/1/05	Dwyer Plumbing	10/20/2005	6/8/2004	6/7/2004	5/20/2004	Osearo	Southview Drive	8 1237 8 1237
Longo	completed repair of broken line/infiltration	Longo Plumbing	3/1/2005	2/7/2005	2/2/2005	1/18/2005	Weber	Southview Drive	12 1228
			11/22/2005	2/8/2005	12/8/2004	12/1/2004	Kerness	Southview Drive	1227
	difficult to deal with	no problems			3/23/2005	1/27/2005	Cavanagh	Southview Drive	FF 1218
		none at this time			1//27/2005	1/11/2005	Globa	Southview Drive	ed 1217
Chris Carlin	sump pump goes into sanitary- re-tv - 5/25 repairec		5/25/2005	4/13/2005	3/30/2005	1/19/2005	Lupichuk	Southview Drive	03 1208
	Miller Drain cleaned lines-revideoed	no problems		2/8/2005	2/7/2005	1/31/2005	Cogley	Southview Drive	3/3 1207
	Inspect remaining street Spring 2006			11/11/2004	11/4/2004	10/28/2004	Kneidinger	Southview Drive	1/20
	Footers tied into sanitary		7/12/2004			4/13/2004		Schwartz Drive)06 5240
	Sump pump overflow to sanitary		6/1/04			6/4/2004		Ruth Avenue	Pag 1023
	Working on Problem 12/22/05			6/24/2005	6/16/2005	6/1/2005	Fiorelli	Ruth Avenue	e 3 1018
5/19/2005		no problem found no problem found			6/21/2005 6/15/2005	5/9/2005 5/20/2005	Shouse Maguire	Ruth Avenue Ruth Avenue	0 of 5 1010
PLUMBER	NOTES	NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	ADDRESS
Township Repair	Inspections In Process	No Problems Found	No Pro	t Suspended	Enforcement Suspend	nt Repaired	Enforcement Repaired	Enforcement Pending	Enforc

755									
Spaeder	Faulty sanitary piping Downspouts to sanitary (outside) Footers tied into sanitary Sump pump to sanitary lines to dirty to tv - portion of line sunk/broken	tv'd 6/22/05 to verify	11/17/2000 4/13/2000 ? 8/3/2004 4/16/2005	2/25/2005	2/9/2005	10/10/2000 3/14/2000 3/21/2003 7/13/2004 1/3/2005	Borowicz	West 22nd Street West 24th Street West 25th Street West 35th Street West 51st Street	Case 2706 3045 2802
	Outside drains to sanitary Chris Carlin televised w Phil Parking lot drain to sanitary - Rocco's Tavern	Can't get into cleanout ? can't find cleanout No problem found	11/1/02 10/30/2002		5/5/2005	6/18/2002 8/10/2004 7/27/2005 7/24/2004 7/28/2004 9/27/2002	Powell Phillips McMaster Horvath	West 11th Street West 12th Street	1:05-cv-00059- 3423 4040
	Footers tied into sanitary	no problem found	6/11/2001		5/5/2005	3/29/2001 5/3/2005	Perkins Church	Washington Avenue Washington Avenue	MBC 5202 5440
	Sump pump to sanitary Downspouts to sanitary		3/12/2003			4/7/2000		Stuart Way Tramarlac Lane	Docum 316
	reinspect in fall	c/o found & repaired		2/3/2006	1/25/2006	5/24/2005	Ferretti	St. Mary Drive	
Ed Ketsel	Working on Problem 1/3/06 Bill Morewood Plumbing Goellner	no problem found no problem found 4 to 6 Connection	9/12/2005 7/29/2005 8/11/2005	6/24/2005 6/3/2005 6/24/2005 6/15/2005	6/2/2005 6/16/2005 6/14/2005 5/26/2005 6/16/2005 6/8/2005	5/6/2005 5/10/2005 6/3/2005 5/10/2005 5/20/2005 5/20/2005	Grady Maier Rahner Zalas DiStefano Kostef	St. Ann Drive	3-12 Filed 03 1178 1243 1243
	Footers tied into sanitary	no problem found	2/14/2003 12/15/2005	5/26/2005	5/18/2005 5/26/2005	2/10/2003 4/27/2005 5/3/2005	Wakulin Pakela	St. Ann Drive St. Ann Drive St. Ann Drive	3/31/200 1105 1166
Chris Carlin	NonResponsive Working of Problem 12/15/05	no problem found		5/24/2005 11/24/2004	5/25/2005 5/19/2005 11/22/2004	5/9/2005 5/3/2005 11/12/2004	Fries Pelkowski Easly	Spring Valley Drive Spring Valley Drive Spring Valley Drive	
	Footers tied into sanitary Chris Carlin repaired? - Needs Inpsected?	no problem found	3/1/03		6/21/2005	2/24/2003 5/23/2005	Wynne Campbell Graham	Spring Valley Drive Spring Valley Drive Spring Valley Drive	e 31 of 5 1206 1225
PLUMBER	NOTES	NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	ADDRESS
Township Repair	Inspections In Process	No Problems Found	No Pi	Enforcement Suspended	Enforcemen	nt Repaired	Enforcement Repaired	Enforcement Pending	Enforc

Page 32 of 50

Case 1:05-cv-00059-MBC 4220	Docu 2130	ment (1767 2030	38-12 1301	ed 2052 Fi 2061	3/3 DDRI	1/2006 Enforc
7 Zuck Road 0 Zuck Road Zuck Road Zuck Road	2 Zimmerly Road Zimmerly Road		West 54th Street West 54th Street	West 51st Street West 51st Street	SS STREET	Enforcement Pending
	Schreiber Bizzaro	Mikolajczyk	Pietruszak	Heglund Corsi	NAME	Enforcement Repaired
8/6/2003 4/3/2001 7/9/2004 7/9/2004	12/13/2004 1/7/2005	2/11/2004 12/17/2004	5/24/2005 5/20/2003	12/7/2004 12/3/2004	1ST INSPECT	nt Repaired
Cutri/Agost Foht	1/5/2005 2/9/2005	2/2/2005		12/16/2004 12/21/2004	TV INSPECT	Enforcemen
	2/25/2005			12/22/2004	ENFORCEMT	Enforcement Suspended
2/2/2004 8/2/2001 8/10/2004 8/10/2004		2/25/2004	٠.	4/15/2005	REPAIR	No Pro
	no problem found down spouts	dirty lines		suspend action	NO VIOLATION	No Problems Found
Footers tied into sanitary downspouts to sanitary Mobile Home Park - multiple violations Mobile Home Park - multiple violations	Goes Out High (Enforcement suspended 9/1/05)	Outside drains to sanitary	shower stall over cleanout Sump pump to sanitary		NOTES	Inspections In Process
					PLUMBER	Township Repair

KEARSARGE I/I INVESTIGATION (Late 2005 / Early 2006)

Case 1:05-6 60 6002 6013	cv-00059 5968 5976	-MBC Do 5953 5955 5958 5958	cumen 5947 5950		Filed 03/31/ 5925 Filed 03/31/ 5921 Filed 03/31/ 5921 Filed 03/31/ 5921 Filed 03/31/ 5921 Filed 03/31/ 5921 Filed 5921 Filed 5921 Filed 5921 Filed 5921 Filed 5922	2006 Page 5905 5811 5822	Ιğ	0 Enforce
Glade Drive Glade Drive Glade Drive Glade Drive Glade Drive	Glade Drive Glade Drive Glade Drive Glade Drive	Glade Drive Glade Drive Glade Drive Glade Drive Glade Drive	Glade Drive Glade Drive	Glade Drive Glade Drive Glade Drive Glade Drive	Glade Drive Glade Dr Glade Dr Glade Dr Glade Dr Glade Drive	Bryant Street Crowell Street Crowell Street Crowell Street	STREET	Enforcement Pendina
Dixson Moyak Gunther Vickey May	Lancaster Garn Sokol Ruscitto	Lakeshore Comm. Guthrie Penberthy Schall Covatto	Coleman Nielsen Helsley	Stubenhofer Tishchenko Stubenhofer	Domodossola Giles Dascanio Caputo Caputo	Robertson Guelcher Watson Decker	NAME	Enforcement Repaired
10/20/2005 11/7/2005 11/7/2005 11/7/2005 10/19/2005 11/18/2005	10/27/2005 11/21/2005 11/21/2005	12/16/2005 10/18/2005 10/24/2005 10/24/2005	10/18/2005	10/18/2005 10/18/2005 10/17/2005 10/18/2005	10/18/2005 9/29/2005 9/30/2005 10/14/2005	12/2/2005 10/13/2005	1ST INSPECT	Repaired
12/15/2005 2/1/2006 12/1/2005 11/1/2005 11/5/2006	2/16/2006	1/31/2006 11/10/2005 12/7/2005 11/8/2005	11/17/2005	12/20/2005 12/20/2005	12/14/2005 11/8/2005 11/8/2005 11/8/2005 11/1/2005	11/9/2005	TV INSPECT	Enforcemen
1/10/2006 2/3/2006				1/10/2006 1/10/2006	2/16/2006 11/29/2005	1/10/2006	ENFORCEMT	Enforcement Suspended
							REPAIR	No Prob
							NO VIOLATION	No Problems Found
No Problem Found No Problem Found	can't find cleanout no access/old house can't find cleanout-found - no problem found	No Problem Found No Problem Found No Problem Found No Problem Found No Problem Found	no lights in basement/spring No Problem Found	can't find cleanout Township to Repair 6" VCP Lateral	No Problem Found No Problem Found No Problem Found	needs to move bush	NOTES	Inspections In Process
							PLUMBER	Township Repair

KEARSARGE I/I INVESTIGATION (Late 2005 / Early 2006)

	No Problem Found				2/7/2006	1/6/2006	Solop	Kuntz Road	
	No Problem Found				11/23/2005	11/7/2005	Jenkins Amoroso	Kuntz Road Kuntz Road	se 1: 1542
	new const hold 4 spring					10/28/2005	Sanford	Kuntz Road	05 1537
				1/10/2006	12/7/2005	10/18/2005	Robson	Kuntz Road	
							Plizga	Kuntz Road	
							Howard	Kuntz Road	
	dirty lines-cleaned - no problem found				1/4/2006	11/30/2005	Vavala	Kuntz Road	
	No Problem Found				2.7.2006	12/16/2005	James	Kuntz Road	
	No Problem Found				1/5/2006	11/30/2005	Sayre	Kuntz Road	
	No Problem Found				1/24/2006	12/9/2005	Johnson	Kuntz Road	
	new const - hold spring					10/28/2005	Buckeye	Kuntz Road	1421
	new const - hold spring					10/28/2005	Buckeve	Kuntz Road	
	new const - hold spring					10/28/2005	Sanford	Kuntz Road	ocur 1403
	No Problem Found				1/10/2006	11/29/2005	Cirillo	Glade Drive	ne 6123
							Cornman	Glade Drive	
	Township to Repair 6" VCP Lateral			2/3/2006	1/4/2006	11/30/2005	O'Connell	Glade Drive	38 6119
						10/28/2005	Weschier	Glade Drive	1 6107
						11/29/2005	Hamilton	Glade Drive	2 6104
	under trailer	Tenant				11/18/2005	Aulenbacher	Glade Drive	6074
					12/15/2005	10/11/2005	Kiehlmeier	Glade Drive	IE 6073
	No Problem Found				11/15/2005	11/4/2005	Long	Glade Dr	le 6065
	needs to move a tree					10/11/2005	Bucheral	Glade Drive	9509
					3/14/2006	10/21/2005	Samler	Glade Drive	3/3 6055
				2/3/2006	1/11/2006	11/4/2005	Naculich	Glade Drive	31, 6044
	No Problem Found				11/3/2005	10/20/2005	Etter	Glade Dr	/2(6043
	can't find c/o - or will install					11/4/2005	Haight	Glade Drive	00 6034
	Township to Repair 6" VCP Lateral				1/24/2006	11/7/2005	Dolak	Glade Drive	6031
				2/3/2006	1/11/2006	11/14/2006	Clark	Glade Drive	6026
		TENANT				12/16/2005	Wheeler	Glade Drive	o 6023
	can't find cleanout					10/20/2005	Nelson	Glade Drive	ge 3 6016
PLUMBER	NOTES	NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	ADDRESS
Township Repair	Inspections In Process	No Problems Found	No Pro	t Suspended	Enforcement Suspended	nt Repaired	Enforcement Repaired	Enforcement Pending	50 Enforce

Case 1 1/41 1801	:05-0 1728					ME 1701	SC 1697		□ 1683	0 1677		ne 1655	nt 1650	38 1642	1636	2 1628	1625	Fi 1616	le 1614	d 0 1613	3/3	31, 1602	/20 1601	1580	60 1572	¹ 1571	o 1562	ge (1561	ADDRESS	f 50 Enforcen
Kuntz Road Kuntz Road Kuntz Road	Kuntz Road Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	Kuntz Road	STREET	Enforcement Pending
Kuhn Menuto Bish	Spracklen Pitto	Corritore	Nieratko	Gibbs	Parker	Clabbatz	Marx	Albert	Tipton	Piszker	Sisco	Detachi	Chapman	∪ŧŧ	Glaspell	Martin	Barricks	Sherred	Harris	Romesburg	Carmichael	Anthony	Romesburg	Horn	Morgan	Wolchik	Chatt	George	NAME	Enforcement Repaired
10/27/2005	11/18/2005 10/31/2005	10/17/2005	11/;14/05	11/14/2005	10/4/2005	10/3/2005	10/18/2005	10/20/2005	10/19/2005	1/9/2006	1/9/2006		11/18/2005	1/6/2006		2/10/2006	1/6/2006	11/7/2005			12/5/2005		12/5/2005	11/29/2005		10/26/2005	10/25/2005	10/25/2005	1ST INSPECT	Repaired
12/13/2005	11/22/2005	11/9/2005	1/10/2006	1/16/2006	11/8/2005	11/10/2005	11/17/2005	2/6/2006		2/20/2006	1/26/2006		1/5/2006	1/18/2006		2/20/2006	3/3/2006	1/4/2006			1/16/2006		1/19/2006	1/10/2006		11/9/2005	11/3/2005	12/1/2005	TV INSPECT	Enforcemen:
		11/29/2005																					2/3/2006	2/3/2006					ENFORCEMT	Enforcement Suspended
																													REPAIR	No Prot
																													NO VIOLATION	No Problems Found
	under porch/or crawl space pipe dirty-clean-reschedule		No Problem Found	reschedule/camera broke	No Problem Found	No Problem Found		dirty lines	dirty lines		No Problem Found	No Problem Found	dirty lines - re done 3/1/06 - no problem found		No Problem Found	No Problem Found					No Problem Found	out of town 12-1/install c/o	No Problem Found	NOTES	Inspections In Process					
																													PLUMBER	Township Repair

KEARSARGE I/I INVESTIGATION (Late 2005 / Early 2006)

	No Problem Found				1/26/2006	1/13/2006	Oborski DeAngelo Van Maele	Pinecrest Drive Pinecrest Drive Pinecrest Drive	Case 5973 5974 5978
	No Problem Found				1/31/2006	1/23/2006	Sauers	Pinecrest Drive	1:05
	No Problem found				2/20/2006	1/13/2006	Kensinger	Pinecrest Drive	
i.e	Enforcement Disregarded - Problem in Main			1/10/2006	11/22/2005	11/7/2005	Cree	Pinecrest Drive	
	No Problem Found				12/15/2005	10/25/2005	Loring	Pinecrest Drive	
							Fiorelli	Pinecrest Drive	
	can't find cleanout					1/9/2006	Laniewicz	Pinecrest Drive	
	No Problem Found				2/1/2006	1/9/2006	Junker	Pinecrest Drive	
							Sanford	Pinecrest Drive	BC 5948
	No Problem Found				2/22/2006	10/21/2005	Frantz	Pinecrest Drive	5942
	No Problem Found				11/22/2005	10/31/2005	Nicotra	Pinecrest Drive	5937
	No Problem Found				2/22/2006	11/28/2005	Lombardo	Pinecrest Drive	O 5936
	c/o near tree-in Florida until April					10/17/2005	Shreve	Pinecrest Drive	S 5931
	No Problem Found				3/1/2006	2/24/2006	Dipko	Pinecrest Drive	E 5930
	No Problem Found				2/23/2006	1/13/2006	Pasko	Pinecrest Drive	ent 5905
				2/7/2006	1/26/2006	1/13/2006	Morrissey	Pinecrest Drive	38- 5904
				1/10/2006	11/2/2005	10/5/2005	Overberg	Patton Street	12 5431
	No Problem Found				11/2/2005	10/17/2005	Sambuchino	Patton Street	5423
	No Problem Found				11/2/2005	10/17/2005	Hampy	Patton Street	
	No Problem Found				11/3/2005	10/19/2005	Scarpelli	Patton Street	ile 5415
				3/1/2006	2/8/2006	10/17/2005	Rimdzius	Patton Street	ed 03 5414
	No Problem Found				12/13/2005	11/18/2005	Pithers	Kuntz Road	3/3 1822
	No Problem Found				2/28/2006	11/8/2005	Spitman	Kuntz Road	
	No Problem Found				11/15/2005	10/19/2005	Miller	Kuntz Road	
	No Problem Found				12/1/2005	10/24/2005	Miller	Kuntz Road	
	No Problem Found				1/6/2006	11/21/2005	Fairchild	Kuntz Road	1807
	some sags in line				11/2/2005	9/29/2005	Thomas	Kuntz Road	
	No Problem Found				11/23/2005	10/18/2005	Orbanek	Kuntz Road	age (1802
PLUMBER	NOTES	NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	ADDRESS
Township Repair	Inspections In Process	No Problems Found	No Pr	Enforcement Suspended	Enforcement	nt Repaired	Enforcement Repaired	Enforcement Pending	5 Enforce

	No Problem Found Township to Repair 6" VCP Lateral				12/6/2005	10/25/2005	Redfoot	Winslow Drive	Cas 1644
	: 1				10/1/10005	10/10/2005	Dimatto	Winslow Drive	e 1 1634
	No Problem Found				11/23/2005	11/18/2005	Sisti	Winslow Drive	
	No Problem Found				2/1/2006	11/28/2005	Swain	Winslow Drive	Ö 1625
							Davis	Winslow Drive	
							Wagner	Winslow Drive	
	No Problem Found				1/5/2006	11/3/2005	Post	Winslow Drive	
9							Barron	Winslow Drive	9- 1611
Chris Carlin	Floor spill repaired and sump pump installed	006	3/8/2006	1/10/2006	11/9/2005	10/12/2005	Bocianowski	Winslow Drive	ME 1604
				3/1/2006	2/9/2006	11/30/2005	Carrol	Winslow Drive	
	No Problem Found				1/17/2006	11/21/2005	Kiser	Winslow Drive	1552
				1/10/2006	12/6/2005	10/26/2005	Delio	Winslow Drive	D 1545
				1/10/2006	11/15/2005	11/4/2005	Lombardozzi	Winslow Drive	8542-1544
	No Problem Found				1/31/2006	1/23/2006	Diloreto	Winslow Drive	un 1533
					12/7/2005	10/21/2005	Desanti	Winslow Drive	e 1532
	No Problem Found				12/13/2005	11/28/2005	Phillips	Winslow Drive	nt 1523
	no admittance/required boots					12/9/2005	Welther	Winslow Drive	38 1522
				2/3/2006	1/11/2006	12/9/2005	Feldman	Winslow Drive	1513
	No Problem Found				12/1/2005	11/14/2005	Ellis	Winslow Drive	2 1502
							McAlpine	Washington Avenue	6111
							Storm	Washington Avenue	-
							Matthew	Washington Avenue	6023
	No Problem Found				11/11/2005	10/27/2005	Eckman	Washington Avenue	
				2/3/2006	1/24/2006	12/9/2005	Kendrath	Washington Avenue	6005
	No Problem Found				1/12/2006	11/28/2005	Plizga	Washington Avenue	5910
				3/6/2006	2/21/2006	1/6/2006	Polanski	Pinecrest Drive	
	No problem Found					1/6/2006	Spiegel	Pinecrest Drive	F 5983
	No Problem Found				2/21/2006	2/15/2006	Zack	Pinecrest Drive	o 5982
	No Problem Found				2/2/2006	1/27/2006	Stickell	Pinecrest Drive	e 5979
PLUMBER	NOTES	AIR NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	ADDRESS
Township Repair	Inspections In Process	No Problems Found		Enforcement Suspended	Enforcemen	nt Repaired	Enforcement Repaired	Enforcement Pending	f 50 Enforce

							Nowak Kazin	Beaver Drive Beaver Drive	Case 1210 1220
							Labenne Dowd	Southview Drive Southview Drive	1:05-0 1170 1177
							Tompkins	Southview Drive	
							Durst	Southview Drive	
							O'Brian	Southview Drive	
							Simmonds	Southview Drive	
							Narus	Southview Drive	
							Goldberg	Southview Drive	C 1135
							Chrzanowski	Southview Drive	
							Mraz	Southview Drive	
							Melaragno	Southview Drive	un 1105
									nent
									38-
				1/10/2006	11/1/2005	10/17/2005	Altman	Winslow Drive	12 1692
							Parker	Winslow Drive	1685
							Nutter	Winslow Drive	
((((((((((((((((((((No Problem Found				2/15/2006	2/6/2006	Bachmaier	Winslow Drive	
Chris Carlin	Floor spill repaired and sump pump installed		3/7/2006	1/10/2006	11/17/2005	10/20/2005	Schwenk	Winslow Drive	
				2	10000		Fox	Winslow Drive	
	blind/will help in spring			3/1/2006	2/15/2006	11/28/2005	Wright Orourke	Winslow Drive	31/2 1655
				3/1/2006	2/14/2006	11/28/2005	Jackson	Winslow Drive	
				3/6/2006	2/16/2006	11/28/2005	Trudnowski	Winslow Drive	6 1659
	No Problem Found				1/12/2006	11/21/2005	Heverly	Winslow Drive	1658
	No Problem Found				2/8/2006	1/23/2006	Wisniewski	Winslow Drive	oa 1651
					1/5/2006	11/18/2005	Santone	Winslow Drive	ge 3 1650
PLUMBER	NOTES	NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	DDRESS
Township Repair	Inspections In Process	No Problems Found	No Pr	Enforcement Suspended	Enforcemer	t Repaired	Enforcement Repaired	Enforcement Pending	50 Enforce

	No Problem Found			2/3/2006	6/7/2005 1/25/2006	5/27/2005 7/5/2005	Dennen leusue Dowling Tibbits Confer Mezler	Larchmont Drive	Case 1:05-cv- 5586 5620 5630
after repair ok	working w/plumber - Chris Carlin - retelevised after repair ok Sags In Pipe - No Problem Found	Wor	4/28/2005	11/3/2004	11/1/2004 6/22/2005	10/27/2004 6/3/2005	Skrypczak Montagna Kline Krauza Skrutsky Pendleton Hedderick	Larchmont Drive	
							l eea Niedzielski Cuneo	Spring Valley Drive Larchmont Drive Larchmont Drive	00cumen 1255 5525 5526
							Mahon Dill Finnecy	Spring Valley Drive Spring Valley Drive Spring Valley Drive	
							Ciacchini Boros Mainzer	Spring Valley Drive Spring Valley Drive Spring Valley Drive	File 1130 1149
							Friedman Lupo Knobloch	Spring Valley Drive Spring Valley Drive Spring Valley Drive	
							Comstock Bolash	Beaver Drive Beaver Drive	
							Petsch Harf Persianoff	Beaver Drive Beaver Drive Beaver Drive	Page 4 P 1225 1235
PLUMBER	NOTES	NO VIOLATION	REPAIR	ENFORCEMT	TV INSPECT	1ST INSPECT	NAME	STREET	DDRESS
Township Repair	Inspections In Process	No Problems Found	No F	Enforcement Suspended	Enforcement	Enforcement Repaired	Enforceme	Enforcement Pending	50 Enforce

STREET

NAME

1ST INSPECT TV INSPECT ENFORCEMT

Enforcement Repaired

Case 1:05-cv-00059-MBC

Larchmont Drive Larchmont Drive

Vilushis Brugger Kubinski Ferretti Sedwick

Larchmont Drive Larchmont Drive

Larchmont Drive Larchmont Drive

Larchmont Drive Larchmont Drive

Deiner Skogsholm Tullio

5/23/2005

6/2/2005

6/24/2005

9/1/2005

no problem found

Larchmont Drive Larchmont Drive

Larchmont Drive

Bartlett DeSante Nicoson

6/3/05

6/7/2005

Enforcement Suspended

KEARSARGE I/I INVESTIGATION (Late 2005 / Early 2006)

No Problems Found

NO VIOLATION

REPAIR

Inspections in Process

Township Repair

PLUMBER

Ed Ketsel

SISANDEZBAS TENE

KEARSARGE PUMP STATION STORAGE & PUMPING STATION UPGRADE ACT 537 SPECIAL STUDY ADDENDUM

TABLE OF CONTENTS

	<u>Page</u>
Update Summary	i
Introduction	1
General	1
Discussion	1
Overflow Events	1
July 31	1
Sept 9	2
Sept 17	3
Dec 23 & 31	3 3
Other Observations	4
K-3 or Summit Meter	4
Discharge Meter Reading	4
Pump Capacity	
Erie City Connection	4 5 5
Bypass Plug Dislodgement	5
Results	6
Overflow Events	6
July 31	6
Sept 9	7
Sept 17	9
Dec 23 & 31	10
Other Observations	11
Erie Connection	11
Sewer Meter K-3	12
Discharge Meter Calculation	12
Bypass Plug Dislodgement	12
Conclusion	13
Overflow Events	13
July 31	13
Sept 9	13
Sept 17	14
Special Study Addendum Alternatives	14
Recommendation	15
Event Selection	15
Concept Selection	16
Tank Selection	17
"Special Study" Plan Conformance	17
Appendices	17

TABLES

Table 1	July 31	Bypass	Page 6a
Table 2	July 31	Storage	Page 6b
Table 3	Sept 9	Bypass	Page 8a
Table 4	Sept 9	Storage (Original)	Page 8b
Table 5	Sept 9	Storage (Deduct for inflow due to displaced plug)	Page 9a
Table 6	Sept 17	Overflow & Storage	Page 10a
Table 7	Dec 23	Overflow & Storage	Page 10b
Table 8	Dec 31	Overflow & Storage	Page 10c
Table 9	Sept 9	Storage (Deduct for influx & add 5,500 gpm pumping	Page 11c

FIGURES

<u>Figure</u>	Description	Page
1	CITY INFLUENT DATE MANOR & BOYER	5a
2	FLOW RATE INCREASES AVAILABLE AT MANOR/BOYER	11a
3	MILLCREEK FLOW SEPT 9, 2004 AT MANOR	11b
4	JULY 31 KEARSARGE METERED EFFLUENT vs. METERED INFLUENT	12a
5	SITE MAP – TANK SIZE IMPACT	17a

UPDATE SUMMARY

The purpose of this update is to detail the changes in the facilities necessary to provide capacity to eliminate existing and future station overloads. The update does not include changes in cost estimates, proposed funding, user charges, implementation schedule and environmental review documentation.

The original study called for continued review of facility sizing during the design and review processes. Overflow events observed during that period revealed that facility sizing was not sufficient to protect against extreme future events. The update describes the increase in storage sizing and forward flow capabilities determined to be necessary to protect against those events.

The comment period is to extend from May 23, 2005, to June 22, 2005. A copy of the article is enclosed.

The changes detailed in the update include an upsized peak flow storage facility from 0.5 MG to 2.3 MG based on projected flows and facility requirements to have managed the September 9, 2004 storm induced flows. That storm had a 40 to 60-year recurrence factor. The storage pumping capacity will be increased to 4,500 gpm also.

The storage requires a 112 ft. diameter footprint vs. the original 80 ft. and has dictated that the tank center be relocated 60 ft. south and that the Authority purchase additional property to accommodate the tank.

Several additional trees will be required to be removed, one a 100 ft. high sycamore. The tank height will be 33 ft. and will not be provided with a roof vs. the original tank at 25 ft. with a roof. The 100-year floodplain, wetlands, and utility separation distances will be complied with.

The forward flow peak will remain the same (4,500 gpm), but the pump speed will be allowed to increase speed in an emergency which will allow them to pump 5,000 gpm. Manual operation may allow greater flows.

The enclosed study reflects the latest changes to adapt the concept to changes in anticipated loadings and design limitations.

KEARSARGE PUMP STATION

STORAGE & PUMPING CAPACITY UPDATE

ACT 537 SPECIAL STUDY ADDENDUM

(Revised May 17, 2005)

INTRODUCTION

In July of 2004 a report was submitted to the PA DEP which was considered a Special Study update for the township's Act 537 Plan. The update was specifically prepared for the Kearsarge pump station to address problems with overflows from the station. The recommendations of the study were based upon past observations at the pump station which did not include any major storms during the period of the study and was forced to utilize incomplete information for overflows in the period prior to the study. Utilizing that information the study recommended that storage be constructed of approximately ½ million gallons for collecting excess flows and that forward pumping capacity of 4,500 gpm be provided.

An update to the study was submitted in August, 2004, which was requested by the PA DEP to address the fact that a larger storage may be necessary. This update was submitted after an overflow event on July 31, 2004, which did indicate that storage volumes greater than the 500,000 gallons may be necessary. The update revised the study recommendation to specify a minimum storage of 500,000 gallons and that further assessment would be made of storms observed through the design period. On September 30, 2004 the PA DEP approved the Act 537 Special Study with the minimum 500,000 gallon storage provision. This report addresses five overflow events that have occurred since the time the report was submitted in July.

DISCUSSION

Overflow Events

Three events would have demanded storage greater than 500,000 gallons. They are those associated with the storms of July 31, September 9, and September 17, 2004. The remaining two events occurred in December (the 23rd and 31st) and, although they were much lesser events and do not impact recommendations, the observations impact the results of the earlier events. Thus all are discussed in this update in order of occurrence.

July 31, 2004 Overflow Event

This overflow was the result of a twenty-nine hour rain event beginning on July 30 at approximately 2:00 p.m. and continuing through until 7:00 p.m. the following day.

App. 547

Several different rainfall gauges were consulted to determine the amount of rain. The following description incorporates a consensus of the meters confirmed by observations.

Rainfall between 2:00 p.m. and 11:00 p.m. of July 30 approximated a total of ½-inch of precipitation. Between 11:00 p.m. and 5:30 a.m. another estimated 2-inches of rain fell. The intensity of the rain then decreased to approximately ½-inch from the period 5:30 a.m. to 3:00 p.m. Then for the period of 3:00 p.m. to 7:00 p.m. rainfall levels reached 1-1/4-inches. Total rainfall recorded by the Summit, McDowell, Landfill, and City rain gauges were between 2-inches to 3.5-inches with the majority of the rain falling between 12:00 a.m. and 5:30 a.m. The highest intensity rainfall occurred at midnight and then again at 5:00 a.m. These two events were followed by a third event at approximately 6:00 p.m. on July 31. This last storm was not observed near the lake nor did it seem to be nearly as extreme at any of the stations located on the north side of the lake ridge. Observations in the vicinity of the top of the ridge and south indicated rainfall of approximately 1-inch during the period 3:00 p.m. to 7:00 p.m. Extreme street flooding was noted throughout the Kearsarge area during this event.

The storm event included no hourly precipitation that would be greater than a one-year recurrence frequency storm but combined it is estimated that it was a five-year frequency storm for a twelve-hour duration and ten years over twenty-four hours. The overflow volumes occurred over two time frames. The first beginning at the time of the second peak flow recorded at McDowell at about .8-inch of rain over an hour period and at Greengarden in the City at approximately .56-inch of rain over that hour. The NOAA weather station at the airport recorded about 1/2-inch of rain within that time frame. The overflow began at approximately 5:30 a.m. and continued until approximately 1:30 p.m. when the bypass was turned off. Little rainfall continued over the next four hours until approximately 6:00 p.m. when the third event began. The overflow was again opened at 7:00 p.m. and it continued open until 2:30 a.m. Most rain had stopped by 7:00 p.m. It is postulated that the earlier drenching of the soil with the high intensity rainfall around midnight saturated the soils and when the second storm began at approximately 5:00 a.m., the soil storage had been exceeded and sump pumps, which are believed connected to the sanitary sewer system, began pumping to protect basements from storm water which resulted in an overload of the sanitary system. The first storm was controlled at the station. The second overflow event at 7:00 p.m. required pumps to be placed at two different manholes in the system to prevent flows from backing up and entering basements. Total bypass flows for the entire period are estimated at 2.295 MG including flows discharged from manholes.

September 9, 2004 Overflow Event

This was created by a storm event associated with residuals of a hurricane. The overflow event began at 2:00 a.m. on September 9th when the bypass was first opened and continued for 20 plus hours. The bypass was closed around 12:15 a.m. on September 10. The rain first began about 5:00 p.m. on September 8. By 11:00 p.m. 1-inch of rain had fallen and increased in intensity throughout the early morning hours.

The best rainfall information available was the Summit Township meter with approximately 1-inch of rain falling between the period 10:30 p.m. and midnight on September 8 and approximately 1-inch of rain falling between the period 12 midnight and 1:00 a.m. Another .4-inch of rain fell between the period of 1:00 a.m. and 2:00 a.m. It is concluded that in the period of 5:00 p.m. and 5:00 a.m., a twelve-hour period. between 4-1/2 and 5-inches of rain fell. A 4-inch rainfall over a twelve-hour period is given as a recurrence frequency of 30 years. A 4-1/2-inch at 50 years and a 5-inch at 70 years. The one-hour was approximately a 1-year storm while the 2-hour was about a 5year recurrence and the 3-hour was about a 10-year recurrence.

During this storm three pumps were sent into the system operating at three different manholes in order to pump sewer levels down to keep levels at or below basement elevations. Total flows bypassed during this event are estimated at 6.0 MG. Of that number, 800,000 gallons had been discharged from the system manholes and 600,000 gallons was originally believed due to flooding of manholes caused by backed up stream waters caused by a downed tree (at approximately 4:15 AM flow inexplicably increased above influent sewer surcharge capacity). This latter volume was later attributed to a cross connection with the stream and estimated at 1,260,000 gallons.

September 17, 2004 Overflow Event

This overflow was again the result of a rain attributed to the residual impact of a hurricane. The rain event began with relatively heavy rain at approximately 6:00 a.m. on September 17, 2004. The rain event averaged about 1-1/2-inches over about a ten-hour period with the majority of the rain falling in the first two hours (approximately 0.5-inch in the first hour and 0.3-inch in the second hour). Three rain gauges were checked for information and all three agreed rather well. The actual rainfall intensities are all less than one-year frequency occurrences. This rainfall event was not a major event.

Overflow at the station began at approximately 10:55 a.m. Unlike other storms this storm began with relatively small flows and it was not until the majority of the rain stopped that flows hit higher levels (complications involved in the assessment included power failures). The overflow volume or bypass volume is estimated at 1.9 MG between the period 10:00 a.m. and 11:30 p.m. Nearly half the bypass volume occurred in the period 5:00 p.m. to 8:30 p.m. during which time only about .15-inch of rain fell. The rain entirely stopped at 7:00 p.m.

December 23 and 31, 2004 Overflow Events

On December 23, 2004, there was an overflow due to rainfall of \(\frac{1}{2} \)-inch over a six-hour period. This event began at about 11:00 AM. The overflow peaked at 1:00 PM at flows of 5,800 gpm but was not stopped until 3:00 PM.

The event on December 31, 2004, was first reported at 9:30 AM and was associated with a snow melt with some rain (1/2-inch over twelve hours). The bypass began at 8:45 AM when the bypass was opened six turns with flows of 4,500 gpm. The bypass was opened

App. 549

to ten turns at 10:30 AM with flows at 5,000 gpm. The meter began to malfunction but at 11:50 PM flows began to recede reaching 4,500 gpm at 11:55 with only two pumps operating. At 3:00 PM the bypass was closed to three turns but flows remained above the station capacity until 7:00 PM. An investigation during that period revealed an old bypass plug had been dislodged and stream waters were back flowing into the pump station. Flows approximating 1,000 gpm were estimated to be entering through the cross connection with about 1 foot of head. The writer observed that condition at 3:30 PM. At that time stream levels were at the crown of the 20-inch ID pipe supporting the old flap gate. That gate was approximately 4-inches agape at the bottom allowing stream waters entry into the Beaver Run gravity sewer just prior to its entry into the pump station. The inflow is downstream from the sewer flow meter K-1. Thus, that meter's results were not impacted by the inflow. Investigations the following Monday, once stream flows receded, found the concrete plug, placed in the overflow at the wing wall, to have been dislodged.

Other Observations

K-3 or Summit Meter

During the assessment of these storms' impacts on the Kearsarge pump station, it was determined that the information being provided for the meter that measures the influent flow at the station from Summit Township termed the "Beaver Run Relief Sewer" was being calculated based upon an 18-inch diameter sewer rather than the actual 24-inch diameter sewer.

Discharge Meter Reading

Because of high flow indications, elongated discharge periods, and the extreme rapid changes in station discharge rates, it was decided to again calibrate the Kearsarge meter by performing drawdown tests. Drawdown tests were completed on September 30, 2004. The results are found in Appendix A. Those tests indicated that the actual meter reading should have been 135% of the given meter reading. Previous attempts at calibration through drawdown had indicated the percentage to have been between 120% and 125%. Overflow volumes given above have been corrected for the newly calculated meter calibrations. Since the overflow values and calculated storage needs for the three storms described above exceed the earlier storms' values, there is no need to correct the earlier results. The design storm will most likely be one of the three recent events recorded in July and September.

Pump Capacity

Pump #1 motor failed toward the end of the September 9th overflow event. As a result the motor was removed and rewound and a new standby motor was ordered (the motor is now on hand). The pump motor was repaired, returned, and installed prior to the September 17th storm event. During the drawdown tests pump #1 was observed to be

App. 550